

**STATE OF WEST VIRGINIA**  
**Department of Environmental Protection**  
**Environmental Enforcement**  
**NOTICE OF VIOLATION**

Violation No **W23-47-024-TJC**

To the Operator or Agent of:

Facility Name: **Parsons-Davis Core Borings** Permit No. **WVR112141**

Permittee or Individual: **GREENMAN-PEDERSEN, INC.**

Located at or near: **Parsons, in Tucker** County

Representative: **DOUGLAS ROBB** Date: **11/14/2023** Time: **14:02**

Address / phone number: **11000 ROKEN LAND PARKWAY, SUITE 500, COLUMBIA, MD 21044 / 4108803055**

Whereas, an inspection of the above named operation by the undersigned, duly authorized agent of the Secretary, at which the following described condition or practice exists, in violation of Chapter **22**, Article **11**, Section(s) **1 et. Seq.** of the Code of West Virginia and/or Section(s) \_\_\_ of the Rules and Regulations and/or Section(s) **I. & II.** of the Permit referenced above promulgated thereunder in that you:

**Have violated the following terms and conditions of WV/NPDES General Water Pollution Control Permit No. WV0115924, Registration No. WVR112141:**

- 1. Section II.F. - GREENMAN-PEDERSEN, INC. failed to properly implement controls in accordance with standard procedures and as described in the approved SWPPP. Portable temporary bridge stream crossing BMPs that were improperly installed were observed at stream crossings SC-4, SC-5, SC-6, DP-4 and DP-5. Plan sheet 14 of the approved SWPPP site plan shows timbers that are joined together to ensure that sediment does not fall through the installed temporary bridge. The installed timbers that were observed on site were not properly joined together as significant gaps and voids between the timbers were observed. The gaps caused sediment to fall through the installed temporary bridge into the stream channels.**
- 2. Section I.G.- GREENMAN-PEDERSEN, INC. failed to prevent sediment-laden water from leaving the site without going through an appropriate device. This deficiency was observed as a result of the failure to properly implement portable temporary bridge stream crossing BMPs.**

The following corrective measures were discussed with you at the time of this inspection:

**Take measures to correct the aforementioned violations.**

Within **20** days provide a written response to the inspector named below, at the address indicated, detailing the actions taken to abate this violation.

Received by:

**Sent Certified Mail**

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Title



\_\_\_\_\_  
Duly Authorized Agent /  
Inspector

**(304)288-6219**  
\_\_\_\_\_  
Telephone

**tim.j.casto@wv.gov**  
\_\_\_\_\_  
E-mail

**Send Response to the Inspector at the address indicated below:**

WV Department of Environmental Protection  
Environmental Enforcement / WW  
2031 Pleasant Valley Road; Fairmont, WV 26554